

Superintendent's Weekly Activity Report #119
Douthit Hills Student Community, Clemson University Project
Joe Jett





Superintendent's Weekly Activity Report #119
Douthit Hills Student Community, Clemson University Project
Joe Jett



CURRENT CONSTRUCTION ACTIVITIES

EAST ZONE & SITE

- Continued Final Inspections @ Buildings G & F.
- Continued Punch List in Buildings G, F, & E.
- Continued Carpet Install @ Building F.
- Finished Final Paint @ Building F 1ST Floor.
- Began Final Paint @ Building F 2nd Floor.
- Continued Installing Lights & Devices @ Bldg. E.
- Continued Millwork and Accessory Install @ Bldg. E.
- Finished Brick Pavers @ Buildings G & F Entrances.
- Continued Final Grading & Stabilization in East Zone.
- Set Precast for West Pedestrian Bridge.
- Began Curb & Gutter for Parking Lot North of Bldg. B.



Pedestrian Bridge Precast

WEST ZONE & HUB

- Began MEP Trim Out @ Building A.
- Continued Millwork Install @ Building A.
- Continued Painting Walls @ Building A.
- Continued DEFS @ Bldgs. C & D.
- Continued MEP Rough-In @ Bldgs. B, C, & D.
- Continued Framing Walls @ Buildings C & D.
- Finished Downspouts @ Building D.
- Continued Hanging Drywall @ Bldgs. B, C, & HUB.
- Continued MEP Rough-In @ HUB 1st Floor.
- Continued Fire Protection R/I @ HUB 2nd & 3rd Floor.
- Continued Metal Panel Installation @ HUB.



Kite Hill Water Tower



Superintendent's Weekly Activity Report #119
Douthit Hills Student Community, Clemson University Project
Joe Jett



NEXT WEEK'S ACTIVITIES

EAST ZONE & SITE

- Continue Final Inspections @ Buildings G & F.
- Continue Punch List in Buildings G, F, & E.
- Continue Carpet Install @ Building F.
- Finish Final Paint @ Building F 1st Floor.
- Continue Installing Lights & Devices @ Bldg. E.
- Continue Millwork and Accessory Install @ Bldg. E.
- Begin HUB Spine Trench Drain Install.
- Continue Final Grading & Stabilization in East Zone.
- Finish Curb & Gutter for Parking Lot North of Bldg. B.



East Zone Overview

WEST ZONE & HUB

- Begin Air-side Start Up & Commissioning @ Bldg. A.
- Continue MEP Trim Out @ Building A.
- Continue Millwork Install @ Building A.
- Continue Painting Walls @ Building A.
- Continue DEFS @ Bldgs. C & D.
- Continue MEP Rough-In @ Bldgs. B, C, & D.
- Continue Framing Walls @ Buildings C & D.
- Continue Hanging Drywall @ Bldgs. B, C, & HUB.
- Continue MEP Rough-In @ HUB 1st Floor.
- Continue Fire Protection R/I @ HUB 2nd & 3rd Floor.
- Continue Metal Panel Installation @ HUB.



Building E Desk Installation



Superintendent's Weekly Activity Report #119
Douthit Hills Student Community, Clemson University Project
Joe Jett



CURRENT WEEK




Rain Days This Week = 0

Rain Days to Date = 71



TOTAL PROJECT LABOR





Superintendent's Weekly Activity Report #119
Douthit Hills Student Community, Clemson University Project
Joe Jett



TOTAL PROJECT LABOR

	TRADE CONTRACTORS ON-SITE	
Subcontractor	Trade	Number of Employees
Holder Construction Company	General Contractor	35
Accessories Unlimited	Accessories	2
Brightview Landscape Development	Hardscape & Landscape	11
Cabinets By Design	Millwork	9
Carolina Fire Protection	Sprinklers	13
Elite Flooring	Tile	3
Feltman Brothers	Masonry - West	0
First Choice Glass	Glazing	4
Gainesville Mechanical	Mechanical	9
Gill Plumbing	Plumbing	37
Graham Hodge	Glazing - HUB	0
Gregory Electric	Electrical – HUB	11
Johnson Controls	Controls	6
Johnsons Modern Electric	Electrical	33
King Asphalt	Asphalt	0
Kone	Elevators	2
Labor Finders	Labor Force	14
Metro Power	Sitework Electrical	3
Nations Roofing	Roofing	3
Palmetto Waterproofing	Waterproofing	1
Precision	Concrete	0
Professional Door	Doors & Hardware	3
Pyramid Masonry	Masonry - HUB	0
Reeves Young	Site Grading & Utilities	13
Rival Construction Inc.	Concrete	0
Sears Contract	Drywall/Metal Trusses	108
Sentential Maintenance	Construction Cleaning	10
Simplex	Controls	7
Southern Mechanical Inc.	Mechanical/Plumbing	74
Specialty Finishes	Painting	14
Steel Toe	Labor Force	6
TG Welding	Misc. Steel	6
Tree South	Arborist	0
TOTAL		437



Superintendent's Weekly Activity Report #119
Douthit Hills Student Community, Clemson University Project
Joe Jett



SAFETY REPORT

• Total Man Hours Worked This Week: 21,010

• Total Man Hours on Project: 1,304,688

• Crafts On Project This Week: 25

• OSHA Recordable Rate: 3.88



INSPECTIONS/TESTING REPORT

- BLE Above Ceiling Inspection (Corridors) Building E 2nd and 3rd Floor
- BLE Electrical Final (Dorm Rooms) Building F 1st and 2nd Floor
- CC&I Above Ceiling Inspections (Corridors) Building A
- CC&I Above Ceiling Inspection Buildings B & C
- CC&I Framing and In-wall Rough-in Inspection Building B
- Elevator Inpsection Building B
- BLE Soil Compaction & Concrete Testing
- Third Party Inspection Crane



ENVIRONMENTAL REPORT

- Pursuing LEED Silver Certification
- Waste Diverted = 21.215 CY